This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.





FIG. 1

02/25/04

A METHOD FOR CORRECTING A MASK... Kahng et al. Greer, Burns & Crain, Ltd. (B. Joe Kim) Ref. No. 0321.67421 Sheet 2 of 3 (312) 360-0080





17.75

Figure to

GATE SIZING PROBLEM	MINIMUM COST OF CORRECTION PROBLEM
AREA	COST OF CORRECTION
NOMINAL DELAY	DELAY μ+ksigma
CYCLE TIME	SELLING POINT DELAY
DIE AREA	TOTAL COST OF RET

FIG. 3